Large Prototype and HV

How to spent a week dismantling and re-attaching an anode end plate

0

WP Meeting 158, 13.Sep.2012 R. Diener, F. Müller, C. Rosemann

LP HV Problems




- Initial problem: HV of field cage tripped after several hours:
 - 15.0 or 15.5kV: ~11-12h
 - 16.0kV: ~several hours (3 or more)
 - 17.0kV: ~half an hour
- Investigation:
 - Connect 7th strip, all shield plates and dummy modules on single channels, to see if we can locate a source for the trips there
 - Testing started 27.Aug.2012
 - Some damaged HV cables found

LP HV

LP HV Anode Plate

- Seen strange tripping all over the end plate when channel voltage about 2100-2200V
- Setting all to 2000 and raising one by one: shield 8 didn't stand it
- First inspection:







LP HV Anode Plate



- Monday:
 - Opening end plate





• Fixed by cutting out damaged part and re-attaching cable

- Tuesday:
 - Next test: shield 5 had connection to ground (clamped the cable between end plate and field cage → repaired)
- Wednesday:
 - Problems with 7th strip:
 - insulation showed scratches
 - put Kapton on top
- Thursday:
 - More problems with 7th strip
 - Now complete reworking of the insulation (top and bottom):
 - bigger Kapton piece below
 - epoxy around hole in 1st strip
 - shrinking tube
 - some Kapton tape on top



LP HV


LP HV Anode Plate



- Friday:
 - 7th strip OK, but shield 4 can't go over 1200V
 - Opening LP for the 5th time
 - Carbon bridge at Fischer receptacle



- Decision: insulate all shield connections
 - All shield parts dismantled
 - All parts cleaned with isopropanol (carbon traces etc.)
 - Shrinking tube over connectors and wires







- Saturday:
 - Field cage powered up again and everything works
 - Shield set to 2250V, cathode at 16kV
- Sunday:
 - Trip after 9 hours, no currents on the shields or dummy modules → Modules are safe, problem at another place of the LP
 - Fault: unfortunately "trip" was not connected to "kill" on the CAEN power supply
 → tripping has lasted some time
- Monday:
 - Opening field cage to check
 - Cleaning carbon spots
 - Field cage still working
- Starting testbeam preparation



Conclusions



- For a detailed listing of actions see logbook: https://ttfinfo.desy.de/LP1elog/
 - entries from the weekend (8. and 9. Sept.) unfortunately listed on Friday (7.Sept.)
- Next end plate:
 - Cables to shield plates should be as short as possible (easily slip out while inserting end plate)
 - Better HV insulation (cables and end points)
- Next field cage: Connection to the 7th strip should be re-designed
- HV problems will be investigated further after current testbeam effort
- Questions:
 - Should the shield plates be equipped with resistors to limit currents?
 - Would this make problems with response time (slower discharging at trip)?