



Jlab Electropolish Update 8/30/06

J. Mammosser





Outline:

- Current status on S-35
- Current status on A-7
- Process Issues Encountered
- Accomplishments
- Direction Forward
 - A-6 planning





Current Status on S35


- S35 was first used to develop tooling and procedures
- Multiple RF tests with no chemistry were performed (5)
 - Standard procedures used, identified new methods to reduce particulates
 - Degreasing, HPR, Clean assembly and Baking Performed
- First 9-cell EP performed
 - Light EP performed identified many improvements in data acquisition and implemented them



60420D-HPR



S35 Vertical Test Results Summary:



Only the first test had field emission!

All limitations were quenches, last two tests all modes measured (all quenched), quenches were at a verity of stored energy's (no smoking gun)

Conclusion:


Most likely the quenches are located at pits in the surface which are in all cells along the walls, would need thermometry to determine for sure





A-7 As received from Accel

Desy Cavity A7 as Received MHz Pull Dir = FP to FPC CW Freq = 1298.954 07/14/06








Bulk Chemistry Material Removal in um

FPC-end FP-end

Equators 172 163 167 160 179 176 180 165 180



Walls	Left		152	146	157	155	154	153	154	157
	Right	184	181	170	174	182	176	177	166	






Tuning - prior to final chemistry

Desy A7 Tuned After First Electro-Polishing
Pull Dir = FPC to FP


CW Freq = 1297.803 Mhz 08/14/06








A7-60825 First Qualifying Test







A7 - Radiation During Testing







Process Issues Encountered:

Electropolish


- During the bulk chemistry I discovered a problem with the beamline seals which resulted in multiple leaks during the chemistry and heavily damaging the beamline flanges
 - Round seals were used which left a gap at the flange ends
 - Endgroup areas were electrically shielded to reduce etching in the endgroups
 - This allowed for low current density in these areas and caused flange gaps to be most likely in active dilution instead of polishing
- Problem was solved for final chemistry with increasing the cathode surface area in the end-group area
- Flange sealing surfaces were mechanically polished to recover them







Aug







Process Issues Encountered:

- Assembly by hand was difficult with current assembly tooling
 - Two persons and multiple hands on parts
 - Tight spots due to cavity holding plates
 - Nut plates were not critically dimensioned for self alignment
 - No ability to rotate cavity in cage to align after installation





Accomplishments:

- Developed video/particle count tooling to record assemblies
 - Tapes reviewed after each assembly and many improvements identified, some resolved already
 - Others will wait when we get more funding
- Proof of principle for removal of sulfur after EP
 - Degreasing cavity open ultrasonic tank with Hot DI and micro-90, seem to work (no sulfur smell after and good performance)
- Learned from S35 many hard quench limits no field emission, multipacting?
 - Need to review simulation data to know where barriers should be






Direction forward:

- Money is tight, I will only use labor until FY07 funding comes
- A-6 was received (thanks)
 - RF inspection complete
 - Next CMM and RF probe calibration
 - Setup for bulk chemistry
 - Furnace treatment 600C
 - Tuning field flat
 - Qualification testing
- Tooling improvements made
 - Focus is now on particle free assemblies, all will be recorded and analyzed





A6- as received from Accel



CW Freq = 1298.961 MHz 08/30/06

