

CLIC Fabrication

Joel Souza Bedolla^{1,2}

On behalf of the X-Band Production Team

¹Lancaster University Engineering Department: *Graeme Burt*

²CERN, BE-RF Section: *Nuria Catalan Lasheras*


International Workshop on Future Linear Colliders (LCWS19), Sendai, Japan

30/10/2019

Summary

- CLIC fabrication in a nutshell
- Discs
 - TD26 Prototype
 - TD31 Prototype
 - Diffusion bonding issues
- Other technical solutions
 - Halves
 - Rectangular discs
- Conclusions

CLIC Fabrication in a nutshell



TD26

N1

Post-Mortem

More details on
bonding issues
section



N2

**Waiting High
Power test**

Tuned
Baked



N3

**Waiting High
power test**


Tuned
Unbaked



N4



**Assembly on-
going**

More details next
slide



TD26-N4

- Diffusion bonding executed at TMD technologies (UK)
 - 1040 °C x 1h 30 min x 0.06MPa x H₂



TD31

N1

**Assembly on-
going**

Bonding completed
Brazing on-going



New
tooling
tested

N2

**Assembly on-
going**

Bonding completed
Brazing on-going



New
tooling
tested


N3

**Manufacturing
completed**





N4

**Manufacturing
completed**




Baseline for CLIC-380GeV

TD31






140 discs
produced.
0 defects



Bead Pull measurements before bonding are better than we usually see. Phase advance (N1) nearly fulfils the requirements after tuning. Due to extremely good quality Also due to the good alignment and RF contact of the tooling.

TD31 – N1 and N2

- Diffusion bonding executed at Bodycote (FR)
 - 1040 °C x 1h 30 min x 0.06MPa x H2



✓ No banana effect
Reduced disc to disc alignment

! Straightness: 46 μm
A bump during transport

Diffusion bonding issues

- The process is stable and it works
 - The structures are leak-tight!
 - We have some issues with straightness but the main cause is the transport from the assembly table to the furnace.
- Two years ago, it was decided to assess the contribution of diffusion bonding
 - Careful attention to metrology
 - Cross-check with Bead-Pull Measurements
 - Post-mortem analysis



1040 °C



1h 30 min



0.06 MPa




H₂



Optimization


Diffusion bonding issues

- Identical bonding cycles on different days (same supplier) for TD26 N1, N2 and N3.
- N4 different supplier (diameter after bonding was not measured)
- External diameter reduction in average 12 μm
- Observed in structures N1, N2 and N3. Double checked on structure N1.
- The total length of the structure is smaller 25 μm




Diffusion bonding issues

- Bonding of TD31 N1 and N2 performed by the same supplier (TD26-N1-N2-N3).
- However, the oven has been completely refurbished in-between.
- Same trend than TD26: diameter reduction in average 11 μm




TD26-1

- Post-Mortem analysis
- Cutting plan (EDM):
 - Same reference for all the discs
 - Shape of the nose (horizontal)
 - Shape of the nose (vertical)
 - Irises
 - Flatness of the waveguide




TD26-1: Shape of the nose (horizontal)



- Datum references have changed with respect to original measurements.
- Shape seemed to improve according to disc position. G00 is worst than G02
- First traces of EDM cutting residuals observed on G03



TD26-1: Shape of the nose (vertical)



- A cone shape is observed
- The error was diminishing up to G03
- Contamination of EDM cutting on G14




Halves

- Long development process:
 - First trial (bonding - CERN): Good RF before bonding. After bonding, a gap between the halves (10-200 μm) and a shift between the irises of 70 μm (systematic error)
 - Second trial (brazed – SLAC): A gap between irises was introduced to minimize field of filling material leaking to the structure. Alignment with pins. RF conditioning ok. Breakdown activity near the brazing region.
 - A third trial (brazed through irises – SLAC): not yet tested but there is a visual misalignment between the irises.










Halves

- Last development TD26:
 - Two identical halves: 285 mm x 146 mm x 14 mm, damped (no SiC), gap.
- Form tolerance: 4 μm on Zone A (zone near the iris of the whole length)
- Electron beam welding design:
 - Hard copper (no heat treatments above 245 °C) showed shorter RF conditioning
 - Welding lips
- Less components to assembly but bigger risks for manufacturing companies
 - Challenging but feasible








Halves

- We do care about the alignment. Special tooling: Herzian deformation of high precision rings.
- Ready to be produced!






Rectangular discs

- First trial successful at 95% (it was leaking)
 - Caused by the SiC geometry
 - Not related to the bonding problem: the SiC was copper coated.
- Second trial successful at 99% (it was not leaking)



Rectangular discs

- Lancaster University PROton Boosting Extension (PROBE) structure
- High gradient (54 MV/m), side coupled, standing wave, S-Band for Proton Computed Tomography (pCT) scan
- Bonding done. Leak test after brazing of components.
- Straightness of 25 μm



Conclusions

- TD26:
 - N1: Post-mortem finished
 - N4: Brazing operations on-going
- TD31
 - N1 and N2: Brazing operation on-going
- Bonding issues:
 - The diameter reduction (copper sublimation) of 10 μm is confirmed: 6 structures
 - The shape of the nose is changing on both horizontal (collapsing) and vertical shapes (cone shape)
 - The cells are deforming due to bonding
 - Weight is excessive? Already reduced from 0.1 MPa to 0.06 MPa
 - Temperature is too high?
 - Time is too long?
- Halves: Ready for production
- Rectangular discs: Bonding performed on the PROBE structure. Leak test in following weeks.




Engineering

Lancaster
University



Thank you



Questions?