Beam Test Analysis - II

Calice Collaboration Meeting @ Valencia Apr 22, 2022

Yuichi Okugawa

Affiliation:











In collaboration with:
























DESY Test Beam March 2022



Data Quality Checks

- Mapping of the COBs
 - Done during the beam test
 - o Rotation of mappings in Chip 13 & 15
- Determination of Hit Rates
 - Offline beam rate measurements
 - cycles → sec
 - Data quality checks





Mapping Issue

- Chip 13 & 15 were identified to have mapping issue during the test beam.
- Without proper mapping, one cannot identify the correct beam spot.
- The issue could only be identified during the test beam since cosmic rays will not create a spot, wide enough to show the mapping structure.







Fig: Channel mapping of **FEV 11** (not COB)




Mapping Issue

- Chip 13 & 15 were identified to have mapping issue during the test beam.
- Without proper mapping, one cannot identify the correct beam spot.
- The issue could only be identified during the test beam since cosmic rays will not create a spot, wide enough to show the mapping structure.












Layer 2: 3.0GeV MIP Position Scan











Hit Rate Checks

- **Hit rate** is used to check the **data quality** of the signals.
 - During the beam test, the hit rate of the first layer was used to estimate the read beam rate.
 - DAQ software is already equipped with online hit rate monitoring.
 - The attempt was made to check data quality **offline**.
- Evaluation of Noise Rate
 - One needs to know the noise ratio of the detector to evaluate the background events from the data.
 - o Combined with noise rate observed from the off-beam analysis, one can estimate the background during the beam test.
 - This requires hit rate information.
- eg) 1 ms window + 10ms delay = 11 ms / cycle





Photo: Beam Monitor at DESY site (From TB2021-11)





Fig: DAQ software (4.6 GeV Energy Scan)




Position Scan (1)




Layer 0 (First)

Sample) 3GeV_MIPscan_eudaq_run_050480







Position Scan (1)




Layer 0 (First)

Sample) 3GeV_MIPscan_eudaq_run_050480











3GeV_MIPscan_eudaq_run_050490





Summary

Mapping

COB mapping was corrected with rotating mapping of chip 13 & 15

Hit Rate

- o Offline hit rate monitoring was examined.
- Assist data quality check
- Noise analysis is to be done with the hit rate information obtained from the beam test.

Advertisement


CALICE Slack Group







CALICE Slack Group



https://join.slack.com/t/calice-workspace/shared_invite/zt-16403o2zp-nU88X2~Gg1DwJgBcFULzqA

CALICE Slack Group

