

# undulator manufacture and measurement

James Rochford

On behalf of the Helical collaboration

Nov 2008





### Introduction

· Undulator specification

## ·Prototype design, manufacture, testing

- 4m Module design
- Magnet Testing and integration
- · Assembly of 4m module
- · First tests of the final prototype

### Current status

- · Where we are at the moment
- · Plans for the coming months



# Magnet manufacturing spec

Following a pretty extensive R&D programme and modelling study the following specification was developed for the undulators:

Undulator Period 11.5 mm

Field on Axis 0.86 T

Peak field homogeneity <1%

Winding bore >6mm

Undulator Length 147 m

Nominal current 215A

Critical current ~270A

Manufacturing tolerances

winding concentricity 20um

winding tolerances 100um

straightness 100um

NbTi wire Cu:Sc ratio 0.9


Winding blocck 9 layers

7 wire ribbon

This defines the shortest period undulator we could build with a realistic operating margin.



- •150m of undulator
- •Module length
  - Vacuum considerations <4m
  - Collimation <4m
  - Magnet R&D 2m section realistic
- Minimise number of modules



RDK-415D Typical Load Map (50Hz) 1st Stage Heat Load (Watts)


5W

0W



# Magnet manufacture












# Magnet testing



Field maps along the


length of the undulator






Consistency of logging system





Particle Trajectories analysis - SPECTRA within expectations




Quench testing both magnets deliver nominal field



# 4m module assembly

# 4 meter module assembly




Straightness 250um


Alignment scope

align

Axis alignment 1mm

Mag 2 connection






Mag 1 connection








First run of complete system early Sept.



# Successful cool down and fill



# 4m module testing 3



### The 1st cool down was successful

Filled system successfully

Siphon operation seems good

### However had serious problem

Large heat leak evident

Rapid boil off of liquid

Loss of vacuum in magnet bore (Beam tube)

Liquid helium leak into magnet bore

System not stable enough to put current into the magnets

System had to be warmed



### Upon warming

Found no leaks at 300K all <10e-10 into magnet bore


Found very small leaks between He vessel

-insulating vacuum <1e-8 - copper conflate seals

Clear we had a cryogenic leak!

### Had to remove magnets

Complete strip down of the prototype







### Cryogenic leak testing

Created a large open Liquid nitrogen bath

To immerse magnets whilst leak testing


Initially found a leak at the indium seal between magnets

Fixed this by modifying the clamp arrangement

Much more worryingly was we seemed to have a leak through

the magnet structure, on magnet 1 and magnet 2







# Iron yoke Copper bore tube Solder join

The suspected leak path

The leak is strange

Not at a normal interface

Seems to be through the magnet torturous path through resin along copper bore to point where the magnets join

There is a small possibility that the bore tube has ruptured somewhere this is really bad news!, unfortunately we cannot differentiate clearly between these, but the delay times in the leak response indicate the solder leak is much more probable

Leak rate 2e-4 level on magnet 1

Leak rate 2e-7 level on magnet 2





### Further leak tests


Aim: Isolate leaks, difficult in composite structure

Tested magnets independantly

Are now confident only magnet 1 leaks

Original leak seen on magnet 2 - leak on magnet 1 close by







# Fixing the leak 1

Leak fix R&D

Limited options here, magnet is delicate.


Cant simply rerun solder joint

Main ideas centre on creating a secondary seal.

Number or small R&D samples

Find the best method to fix it

- •1 keep existing structure machine in a small groove to fill
  - •need material to cope with differential contraction
- •2 machine away steel flange leaving only the copper tube
  - Sleeve and stycast (fall back solution)







### **R&D** Samples

Different epoxies

All fail under repeated

cycling for CulFe combination

Problem seems to be the

differential contraction

Stycast with a Cu\Cu

Joint works-implication need to
machine away Steel flange


More samples to test using woods metal.

Have some ideas to inset a Steel\Cu ring to act as a filler which can better match the conductivities











### Following leak fix

Check magnet this by cooling with LN2 as for leak tests described earlier Repeat prototype build with an additional step

Once the magnets are integrated in the vac vessel

We will cool using the LN2 circuit and leak check

prior to connecting the turret

If ok we will proceed with the build

### Rebuild of prototype

Should have system closed by Christmas (Aggressive schedule)

### Next cool down

Power magnets to nominal current 1<sup>st</sup> week of the new year