



Damage on Field Cage by Slipped Module

Before the "repair"



After grinding with very fine sandpaper



All resistivity values OK, no disconnection.