

Disassembly Status of S1-G Cryomodule



Disassembly Plan of S1-G Cryomodule



Disassembly of Cryomodule-A in S1-G

Check of Tuner system
(A4/MHI-09 cavity)

No visible trouble, but
rotation of drive shaft was not easy !!




June 15, 2011

Disassembly of Cryomodule-A in S1-G

cutting of 2K Pipes (Ti) by saw



June 23, 2011



Disassembly of Cryomodule-A in S1-G



After cutting of 2K Pipes (Ti)



June 23, 2011

Disassembly of Cryomodule-A in S1-G





Release from GRP,
Setting on support posts,
Moving to preparation area





June 29, 2011

Disassembly of Slide-jack Tuner




July 01,
2011




Re-assembly of Slide-jack Tuner

Rotation of drive shaft is not easy.




(A4/MHI-09 cavity)

Rotation of drive shaft is smooth !!



Measurement of thickness gauge

Check of Slide-jack Tuner



Check of Slide-jack Tuner

