



Since a PCB connector was broken, Yatsukasa-kun tried to connect between a signal cable and a pin in a connector on the DCS board.




6-pin PCB connector (2 mm pitch width) is unavailable in (Japanese) market, so it was prepared by hand (cutting).



A sleeve of a signal line remained on the DCS board, then the connection with the DHCP server lost...



This part can be connected permanently.



This kind of tool is useful for the disconnection!



This connector can (should) be fixed on the DCS board.