3.9GHz Engineering meeting

Report of Contributions

Contribution ID: 0 Type: not specified

Helium vessel welding issues – welder certification – procedure

Monday 27 August 2007 09:05 (20 minutes)

Presenter: MITCHELL, FOLEY

Session Classification: 3.9 GHz

Contribution ID: 1 Type: not specified

Helium vessel status – bellows weldment

Monday 27 August 2007 09:25 (15 minutes)

Session Classification: 3.9 GHz

Contribution ID: 2 Type: not specified

Cavity No. 5 test results

Monday 27 August 2007 09:40 (15 minutes)

Presenter: TIMER

Session Classification: 3.9 GHz

Contribution ID: 3 Type: not specified

Cavity No. 8 status

Monday 27 August 2007 09:55 (15 minutes)

Presenter: FOLEY

Session Classification: 3.9 GHz

Contribution ID: 4 Type: **not specified**

Report on trip to Roark

Monday 27 August 2007 10:10 (15 minutes)

Presenter: REEVES

Session Classification: 3.9 GHz

Other business

Contribution ID: 5 Type: **not specified**

Other business

Monday 27 August 2007 10:25 (15 minutes)

Session Classification: 3.9 GHz

Contribution ID: 6 Type: **not specified**

Trip to AES to observe equator welds and weld preparations

Monday 27 August 2007 09:00 (25 minutes)

Session Classification: 1.3 GHz