






QM7R Vertical Bump



March 14, 2008

No QM7R errors

ML1X vs BPM.20









QM7R sextupole error


ML1X vs BPM.20



ML1X




ML2X




QM7R gradient error


ML1X vs BPM.20



ML1X




ML2X




QM7R sextupole error and gradient error


ML1X vs BPM.20



ML1X



ML2X



What the hell?

- seems like EXT Y and DR Y are opposite
- are EXT millimeters equal to DR millimeters?