


Faraday Rotation System Update

- Laser safety finally approved on Nov. 16.
- Argon Ion laser is in good shape.
- KM Laser
 - Runs in CW mode
 - Not run in mode-lock due to a misalignment



- CM2 misaligned during shipment from KMLab to Wisconsin.
- CM2 misaligned again during shipment from Wisconsin to SLAC.
- Fold Mirror found misaligned as well – the laser beam is near the base at Prism #2 and is at the edge at High Reflector.