





AC71 Scratch on Iris #1cell-#2cell  
from Iris center to input coupler side, 6mm length trace,  
rotation=137deg.

