

- Clean room shutdown at DESY
 - Refurbishment of the clean room is finished
 - Clean room in operation again
 - Preparation and assembly of cavities for next modules is ongoing
- S1-global cavities
 - Two cavities have been selected
 - Z108 and Z109